| <b>Accident Pro</b>                     | ofile  |   |  |                                       |  |  |                     |
|---|--|---|--|---------------------------------------|--|--|---------------------|
| Title                                   |  |   |  |                                       |  |  |                     |
| Explosion cau                           | used by erroneous mix                                      | ing of two chemical prod  | ucts   |                                       |  |  |                     |
| Date/Time o                             | of Major Occurren  | ice   |  |                                       |  |  |                     |
| Start Date                              | 23-03-1999   | End Date  | 23-03-1999                                   |                                       |  |  |                     |
| Event Type                              |  | Reported  | under  |                                       | Seveso II  | Status                                   |                     |
| Other Event                             |  | EU Seveso   | II Directive                                 |                                       | - not know   | n / not applicable                       | e <b>-</b>          |
| Industrial Ac                           | ctivity  |   |  |                                       |  |  |                     |
|   | -  | stribution (excluding LPG                                       | S)   |                                       |  |  |                     |
| Reasons for                             | r Reporting  |   |  |                                       |  |  |                     |
|   |  | 5% of quantity in Colum   | ın 3 of Annex I                              |                                       |  |  |                     |
| ✓ Injury to per                         | sons: >= 1 fatalities, >:                                  | = 6 hospitalizing injuries,                                     | evacuation, she                              | elter-in-place                        | , utility disruption and da  | mage to real esta                        | ate                 |
| Immediate o                             | damage to the environr                                     | ment (according to Anne   | x VI)  |                                       |  |  |                     |
| Damage to                               | property: on-site >2M &                                    | €, off-site > 0.5M &e   | euro;  |                                       |  |  |                     |
| Cross-borde                             | er damage: transbound                                      | lary accidents  |  |                                       |  |  |                     |
| Interesting f                           | or lessons learned.  |   |  |                                       |  |  |                     |
|   |  |   |  |                                       |  |  |                     |
| Accident Re                             | port   |   |  |                                       |  |  |                     |
| Accident de                             | escription   |   |  |                                       |  |  |                     |
| products a<br>chloride. S<br>chemical o | are mixed. It turn<br>Subsequent explo<br>cloud is formed, | s out that some so<br>osions in other cor<br>consisting of chlo | dium chlori<br>ntainers thro<br>rine and chl | ite had be<br>ow pieces<br>lorine dio | violent explosion<br>en put in a contain<br>of the vessels up t<br>xide. A small quar<br>me ground polluti | er holding for some 100 ntity of various | Perric<br>metres. A |
| Accident in                             | volving  |   |  |                                       |  |  |                     |
| Domino ef                               | fects  | Natech events   |  | Transbo                               | oundary effects  | □с                                       | Contractors         |
| Site and inst                           | tallation  |   |  |                                       |  |  |                     |
| Site descrip                            | otion  |   |  |                                       |  |  |                     |
| chemicals                               | warehouse  |   |  |                                       |  |  |                     |
|   |  |   |  |                                       |  |  |                     |
| Installation/                           | Unit description   |   |  |                                       |  |  |                     |
| not given                               |  |   |  |                                       |  |  |                     |

Saturday, April 26, 2025 Page 1 of 3

#### **Substances**

#### **Substances Involved**

The mixing of 3 m# of sodium chlorite (C.A.S. No: 7758-19-2) in a 30 m# vessel holding ferric chloride (C.A.S..No: 7705-08-0) (acidic) caused the explosion, since sodium chlorite can decompose explosively in an acidic environment. The substances generated are toxic (chlorine (C.A.S. No: 7782-50-5), hydrochloric acid (C.A.S. No: 7647-01-0)).

#### **Substances Classification**

| 02. TOXIC                                 |
|---|
| 09 i. DANGEROUS FOR THE ENVIRONMENT - R50 |
| 00. NAMED SUBSTANCE                       |

### **Substances detail**

| Substance                                       | CAS Number | Quanti   | Quantities (t.) |  |  |
|---|------------|----------|-----------------|--|--|
| Substance                                       | CAS Number | Involved | Potential       |  |  |
| sodium chlorite                                 | 7758-19-2  |          |                 |  |  |
| Iron(III) chloride, also called ferric chloride | 7705-08-0  |          |                 |  |  |
| chlorine  | 7782-50-5  |          |                 |  |  |
| hydrochloric acid                               | 7647-01-0  |          |                 |  |  |

## Causes

A mistake was made at the warehouse.

## Consequences

Three people are injured, 2 employees of the installation by missiles thrown out by the explosions and one fireman slightly affected by fumes during fire-fighting operations. Environmental pollution is limited, since it was possible to close off the storm water drains carrying the noxious substances. The toxic cloud did not cause any injuries to the public.

#### Human

| On site  | Quantity | Quantity/Effect                               |
|----------|----------|---|
| Injuries | 2.00     | 2 employees of the installation and 1 fireman |

#### **Environmental**

| Off site | Quantity | Quantity/Effect  |
|----------|----------|--|
| Other    |          | Environmental pollution is limited, since it was possible to close off the storm water drains carrying the noxious substances. |

#### Cost

| On site         | Cost in Euro | Quantity/Effect |
|-----------------|--------------|-----------------|
| material losses |              |                 |

Saturday, April 26, 2025 Page 2 of 3

# **Emergency Response**

Storm-water drain valves were closed, but not immediately. The fireman neutralised the substance concerned (Ferric Chloride - FeCl3) using bicarbonate of soda. Traffic was blocked on the ring road nearby for about an hour. Work to clean up and re-enable safe operation is awaited.

| Emergency Response         | Quantity | Quantity/Effect |
|----------------------------|----------|-----------------|
| On-site systems            |          |                 |
| Off-site external services |          |                 |
| Sheltering                 |          |                 |
| Evacuation                 |          |                 |
| Other                      |          |                 |
| Remedial Measure           | Quantity | Quantity/Effect |
| Decontamination            |          |                 |
| Restoration                |          |                 |
| Other                      |          |                 |

## **Lessons Learned**

### Theme of the Lessons Learned

Other

#### **Lessons Learned**

Measures were taken to stop work in the factory while the installations were secured, and the products spilt (liquid and solid) were cleaned up.

# **Event Profile**

**Publication Date** 

Saturday, April 26, 2025 Page 3 of 3